

ARQUS

Technical information



Other documents available for this product

Technical information for ARQUS executive desks

Technical information for ARQUS executive meeting tables

10 year Warranty

See Warranty statement



Technical information

Types

- Cabinet (1)
- Wardrobe (2)

Cabinet with 2 doors

Carcass

- 18 mm chipboard covered in veneer.

Shelves

- 18 mm chipboard covered in veneer;
- Load capacity – 25 kg.

Doors

- 18 mm chipboard covered in veneer;
- Push-to-open door.

Legs

- Bent and welded round metal structure made of Ø40 mm tube;
- Powder coated metal;
- Plastic feet with height levelling (+10 mm).

Wardrobe

Carcass

- 18 mm chipboard covered in veneer.

Shelves

- 18 mm chipboard covered in veneer;
- Load capacity – 25 kg;
- Pull-out coat hanger, load capacity – 3 kg.

Doors

- 18 mm chipboard covered in veneer;
- Push-to-open door.

Base

- Rectangular welded metal structure made of 50x20 mm tube;
- Powder coated metal;
- Plastic feet with height levelling (+10 mm).

1




2




Range

Cabinet with 2 doors




Wardrobe

L/H




R/H



Additional information

- Cabinet has two shelves included, which can be placed in any of the three openings. Shelf in the middle opening has only 1 fixed height in the centre, while the shelves in the side opening can be adjusted vertically by 192 mm.




!

Always arrives fully assembled, except base.

- Wardrobes shelves in the closed space are fixed. Each shelf in the open space can be adjusted vertically by 128 mm.

- It's recommended to fix the wardrobe to the wall or grounded with counterweights. Fixings are included in the packaging.



!

Always arrives fully assembled, except the base.

!

Important: Furniture with natural veneer décor is sensitive to direct sunlight and colour tone changes can occur over time. Adding new items to the same space as existing veneer products of the same design might result in veneer colour tone variations. Veneer must be protected from deep scratches, intense light and prolonged exposure to liquid stains. It is recommended to follow the veneer cleaning and care instructions.